sales@murada.co.id
www.murada.co.id



VERSA-MATIC Repair Kit Air For 22A398, 22A481

Item **27TZS2777** Mfr. Model **476V007000**

Product Details

Item Reference: **22A481**	Width (in): **2.6**
Brand: **VERSA-MATIC**	Height (in): **0.9**
Weight (lb): **0.22**	Harmonization Code: **4016935050**
Length (in): **6.8**	

Product Description

Air End Repair Kit Compatible with Grainger Part Number 20LR16 20LR17 20LR18 20LR19 20LR20 20LR21 20LR22 20LR23 20LR24 22A398 40XD28 40XD29 40XD30 Compatible with Manufacturer Model Number E5SP5F559C-FP Includes Diverter U-Cup Product Type Air End Repair Kit Compatible with Series 1/2 in E-SERIES ALUMINUM 1/2 in E-SERIES POLYPROPYLENE 1/2 in E-SERIES STAINLESS 1/2 in E-SERIES STAINLESS FP Compatible Connection Media Type Air