sales@murada.co.id
www.murada.co.id



ASCO Valve Rebuild Kit For 3UL87 3UL88, 2HTW4

Item **22ESA49949** Mfr. Model **302120**

Product Details

Item Reference: **2HTW4**	Width (in): **3.7**
Brand: **ASCO**	Height (in): **2.2**
Weight (lb): **0.2**	Harmonization Code: **8481909085**
Length (in): **5.3**	

Product Description

Valve Rebuild Kit For Use With Grainger Item Number 3UL87 3UL88 Includes Bonnet Cap Retaining Clip Retaining Core Assembly Holder Assembly I And M Instructions O-Rings Plugnut/Core Tube Assembly Spring Compression Wrench -