sales@murada.co.id
www.murada.co.id



ASCO Valve Rebuild Kit With Instructions, 1AKY2

Item **22ESA50010** Mfr. Model **302328**

Product Details

Item Reference: **1AKY2**	Width (in): **3.7**
Brand: **ASCO**	Height (in): **2.3**
Weight (lb): **0.34**	Harmonization Code: **8481909085**
Length (in): **5.4**	

Product Description

Valve Rebuild Kit For Use With Grainger Item Number 3UL05 3UL06 3UL07 3UL08 6FAZ5 For Use With Mfr Model Number 8210G087 120/60 110/50 8210G088 120/60 110/50 SD8210G087120/60 110/50A EF 8210G087 120/60 110/50 EF 8210G088 120/60 110/50 Includes Cap Clip Core Assembly Core Tube Assembly Diaphragm/Seat Assembly Instructions O Rings Springs -