sales@murada.co.id
www.murada.co.id



ASCO Valve Rebuild Kit With Instructions, 1AKY6

Item **22ESA50014** Mfr. Model **302276**

Product Details

Item Reference: **1AKY6**	Width (in): **3.7**
Brand: **ASCO**	Height (in): **2.2**
Weight (lb): **0.33**	Harmonization Code: **8481909085**
Length (in): **5.4**	

Product Description

Valve Rebuild Kit For Use With Grainger Item Number 2HTX7 3UL19 3UL22 3UL23 3UL24 4EKU9 4EKV5 4ELH3 For Use With Mfr Model Number 8210G095 24/60 8210G095 24/60 8210G095 120/60 110/50 8210G095 240/60 220/50 8210G095 480/60 440/50 8210G095 240/60 220/50 EF 8210G095 120/60 110/50 JKF 8210G095 120/60 110/50 SC 8210G095 120/60 110/50240358-001 Includes Cap Clip Core Assembly Core Tube Assembly Diaphragm/Seat Assembly Instructions O Rings Springs -