sales@murada.co.id
www.murada.co.id



ASCO Valve Rebuild Kit Use w/4EKR9, 4ELP1

Item **22ESA50026** Mfr. Model **302273V**

Product Details

Item Reference: **4ELP1**	Width (in): **2.3**
Brand: **ASCO**	Height (in): **5.2**
Weight (lb): **0.5**	Harmonization Code: **8481909085**
Length (in): **3.8**	

Product Description

Valve Rebuild Kit For Use With Grainger Item Number 4EKR9 For Use With Mfr Model Number 8210G002V 120/60 110/50 Includes Piston Disc Holder Assembly Piston Spring Retaining Ring And Bonnet Gasket