sales@murada.co.id
www.murada.co.id




# ASCO Valve Rebuild Kit For Use w/4EKP6, 4ELP2

Item **22ESA50027** Mfr. Model **302280V**

## Product Details

| | |
|---|---|
| Item Reference: **4ELP2** | Width (in): **3.5** |
| Brand: **ASCO** | Height (in): **4.2** |
| Weight (lb): **0.5** | Harmonization Code: **8481909085** |
| Length (in): **3.5** | |

## Product Description

Valve Rebuild Kit For Use With Grainger Item Number 4EKP6 6FAX2 For Use With Mfr Model Number 8210G004V 120/60 110/50 EF8210G004V120/60 110/50DA Includes Piston Disc Holder Assembly Piston Spring Retaining Ring And Bonnet Gasket