sales@murada.co.id
www.murada.co.id



ASCO Valve Rebuild Kit Use w/4EKY7 and 4ELF9, 4ELU2

Item **22ESA50049** Mfr. Model **304350**

Product Details

Item Reference: **4ELU2**	Width (in): **2.8**
Brand: **ASCO**	Height (in): **5.7**
Weight (lb): **0.3**	Harmonization Code: **8481909085**
Length (in): **4.2**	

Product Description

Valve Rebuild Kit For Use With Grainger Item Number 4EKW6 4ELF9 For Use With Mfr Model Number 8262G200 120/60 110/50 SC 8262G200 120/60 110/50240664-001 Includes Bonnet Gasket Bonnet Gasket And Spring Washer Core Cover Disc Holder Assembly Disc Holder Spring Plug nut Assembly Retaining Cap And Clip Solenoid Base Sub-Assembly Spacer