sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 2HTP7, 6DYC6

Item **22ESA50095** Mfr. Model **302787**

Product Details

Item Reference: **6DYC6**	Width (in): **2.3**
Brand: **ASCO**	Height (in): **5.2**
Weight (lb): **0.26**	Harmonization Code: **8481909085**
Length (in): **3.7**	

Product Description

Rebuild Kit For Use With Grainger Item Number 2HTP7 For Use With Mfr Model Number 8030G010 120/60 Includes Body Gasket Core Assembly Core Spring Gasket Stem Retaining Cap