sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 2HTP8, 6DYC7

Item **22ESA50096** Mfr. Model **302788**

Product Details

Item Reference: **6DYC7**	Width (in): **2.3**
Brand: **ASCO**	Height (in): **5.2**
Weight (lb): **0.32**	Harmonization Code: **8481909085**
Length (in): **3.7**	

Product Description

Rebuild Kit For Use With Grainger Item Number 2HTP8 For Use With Mfr Model Number 8030G013 120/60 Includes Body Gasket Core Assembly with Core Spring Solenoid Base Sub-Assembly Stem Gasket