sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 2HTP9, 6DYC8

Item **22ESA50097** Mfr. Model **302789**

Product Details

Item Reference: **6DYC8**	Width (in): **3.6**
Brand: **ASCO**	Height (in): **2.1**
Weight (lb): **0.25**	Harmonization Code: **8481909085**
Length (in): **5.2**	

Product Description

Rebuild Kit For Use With Grainger Item Number 2HTP9 For Use With Mfr Model Number 8030G016 120/60 Includes Body Gasket Core Assembly Core Spring Gasket Stem Retaining Cap