sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 5LU41, 6DYD8

Item **22ESA50107** Mfr. Model **304033**

Product Details

Item Reference: **6DYD8**	Width (in): **2.3**
Brand: **ASCO**	Height (in): **5.2**
Weight (lb): **0.51**	Harmonization Code: **8481909085**
Length (in): **3.7**	

Product Description

Rebuild Kit For Use With Grainger Item Number 5LU41 For Use With Mfr Model Number 8222G005 120/60 110/50 Includes Body Gasket Core Assembly Core Spring Piston Assembly Piston Stop Retaining Clip Solenoid Base Gasket