sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 5LU21 5LU22, 6DYG5

Item **22ESA50133** Mfr. Model **318247**

Product Details

Item Reference: **6DYG5**	Width (in): **3.7**
Brand: **ASCO**	Height (in): **2.2**
Weight (lb): **0.23**	Harmonization Code: **8481909085**
Length (in): **5.4**	

Product Description

Rebuild Kit For Use With Grainger Item Number 3UM33 5LU21 5LU22 For Use With Mfr Model Number 8040H008 120/60 110/50 8040H006 120/60 110/50 8040H007 120/60 110/50 Includes Body Gasket Core Assembly Core Spring Core/Disc Core/Guide Rider Ring Solenoid Sub-Assembly