sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 1ALA6 1ALA8 2HUA8 2HUA9, 6DYG7

Item **22ESA50134** Mfr. Model **322670**

Product Details

Item Reference: **6DYG7**	Width (in): **2.2**
Brand: **ASCO**	Height (in): **5.3**
Weight (lb): **0.34**	Harmonization Code: **8481909085**
Length (in): **3.7**	

Product Description

Rebuild Kit For Use With Grainger Item Number 1ALA6 1ALA8 2HUA8 2HUA9 For Use With Mfr Model Number 8210P093 100-240 8210P093 24-99 8210P094 100-240 8210P094 24-99 Includes Body Gasket Core Assembly Core Spring Core/Disc Core/Guide Rider Ring Solenoid Sub-Assembly