sales@murada.co.id
www.murada.co.id




# ASCO Rebuild Kit for 1ALB1 1ALB5, 6DYG9

Item **22ESA50136** Mfr. Model **322676**

## Product Details

| | |
|---|---|
| Item Reference: **6DYG9** | Width (in): **2.4** |
| Brand: **ASCO** | Height (in): **5** |
| Weight (lb): **0.3** | Harmonization Code: **8481909085** |
| Length (in): **3.8** | |

## Product Description

Rebuild Kit For Use With Grainger Item Number 1ALB1 1ALB5 For Use With Mfr Model Number 8210P087 100-240 8210P088 100-240 Includes Body Gasket Core Assembly Core Spring Core/Disc Core/Guide Rider Ring Solenoid Sub-Assembly