sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit for 2LBG5, 6DYK0

Item **22ESA50156** Mfr. Model **304354V**

Product Details

Item Reference: **6DYK0**	Width (in): **2.3**
Brand: **ASCO**	Height (in): **5.2**
Weight (lb): **0.3**	Harmonization Code: **8481909085**
Length (in): **3.7**	

Product Description

Rebuild Kit For Use With Grainger Item Number 2LBG5 For Use With Mfr Model Number 8262G208V 120/60 110/50 Includes Body Gasket Bonnet Gasket Core Assembly Core Spring Plugnut/Core Tube Solenoid Base Assembly Valve Bonnet