sales@murada.co.id
www.murada.co.id



ASCO Rebuild Kit, 6DYK2

Item **22ESA50158** Mfr. Model **310420HW**

Product Details

Item Reference: **6DYK2**	Width (in): **3.4**
Brand: **ASCO**	Height (in): **4.2**
Weight (lb): **0.55**	Harmonization Code: **8481909085**
Length (in): **3.6**	

Product Description

Rebuild Kit For Use With Grainger Item Number 5LU30 For Use With Mfr Model Number 8221G007HW 120/60 110/50 Includes Bleed Gasket Body Gasket Core Assembly Core Spring Flow Control Lip Seal Support Pilot Gasket Piston Piston Assembly Piston Spring Snubber Solenoid Base Gasket Solenoid Base Sub-Assembly