
sales@murada.co.id
www.murada.co.id



THOMAS Rebuild kit For 5Z683, 2KFV5

Item **23GYW15932** Mfr. Model **1904**

Product Details

Item Reference: **2KFV5**	Width (in): **4.5**
Brand: **THOMAS**	Height (in): **1.2**
Weight (lb): **0.22**	Harmonization Code: **8481909085**
Length (in): **8.5**	Country of Origin: **United States**

Product Description

Rebuild kit For Use With Mfr Model Number T-617 HDN Includes Cylinder Sleeve O-Rings Piston Cup and Retainer Screws Valve Flappers Rebuild Kit For Use With T-617 HDN