



## DAYTON Pump Repair Kit TPV For 22A598 34TJ44, 22A614

Item **27VRC2837** Mfr. Model **22A614**

### Product Details

Item Reference: <b>22A614</b>	Width (in): <b>11.7</b>
Brand: <b>DAYTON</b>	Height (in): <b>4.1</b>
Weight (lb): <b>2.3</b>	Harmonization Code: <b>8484900000</b>
Length (in): <b>13.5</b>	Country of Origin: <b>Japan</b>

### Product Description

Pump Repair Kit Check Ball Material Santoprene Compatible with Grainger Part Number 22A598 34TJ44 3HJX1 3HJX1A Compatible with Manufacturer Model Number 22A598 34TJ44 3HJX1 3HJX1A Diaphragm Material Santoprene Number of Check Balls 4 Number of Diaphragms 2 Number of O-Rings 12 Number of Seals 0 Valve Type Ball Product Type Fluid End Repair Kit Media Intake Pressure (Maximum) Not Applicable Compatible with Pump Type Air Operated Double Diaphragm Pump