



BANJO Repair Kit for Poly Pump, 42EA82

Item **27LKM7354** Mfr. Model **12000A**

Product Details

Item Reference: 42EA82	Width (in): 5.8
Brand: BANJO	Height (in): 2.6
Weight (lb): 0.76	Harmonization Code: 8481805090
Length (in): 8	Country of Origin: United States

Product Description

Repair Kit for Poly Pump Fits Brand Banjo For Use With Grainger Item Number 21C982 6ANP1 6ANP2 6ANP3 For Use With Mfr Model Number 200P-3 200P6PRO 200PH-5 205PB Includes (5) Vane Impeller Body Oring Pump Slinger Seal Assembly