



## ASC Valve Rebuild Kit For Use w/4EKP6, 4ELP2

Item **22ESA50027** Mfr. Model **302280V**

### Product Details

|                              |                                         |
|------------------------------|-----------------------------------------|
| Item Reference: <b>4ELP2</b> | Width (in): <b>3.5</b>                  |
| Brand: <b>ASCO</b>           | Height (in): <b>4.2</b>                 |
| Weight (lb): <b>0.5</b>      | Harmonization Code: <b>8481909085</b>   |
| Length (in): <b>3.5</b>      | Country of Origin: <b>United States</b> |

### Product Description

Valve Rebuild Kit For Use With Grainger Item Number 4EKP6 6FAX2 For Use With Mfr Model Number 8210G004V 120/60 110/50 EF8210G004V120/60 110/50DA Includes Piston Disc Holder Assembly Piston Spring Retaining Ring And Bonnet Gasket