



## ZURN WILKINS RP Repair Kit, 41TL60

Item **22IVM50405** Mfr. Model **RK34375**

### Product Details

|                               |                                       |
|-------------------------------|---------------------------------------|
| Item Reference: <b>41TL60</b> | Width (in): <b>5</b>                  |
| Brand: <b>ZURN WILKINS</b>    | Height (in): <b>2</b>                 |
| Weight (lb): <b>0.31</b>      | Harmonization Code: <b>8481909085</b> |
| Length (in): <b>7</b>         | Country of Origin: <b>China</b>       |

### Product Description

RP Repair Kit Fits Brand Zurn For Use With Grainger Item Number 45K857 45K858 For Use With Mfr Model Number 12-375XL 34-375XL Includes Check assembly #1 and #2 O-Ring Cover O-Ring Housing Inlet O-Ring Housing Outlet O-Ring Seat O-Ring Sleeve Relief Valve Seat Relief Valve Spring Relief Valve Stem Assembly