



STENNER Pump Head Repair Kit 1/4in PC For35U539, 29FJ87

Item **27YBJ1723** Mfr. Model **QP102KG1**

Product Details

Item Reference: 29FJ87	Width (in): 9
Brand: STENNER	Height (in): 8
Weight (lb): 0.67	Harmonization Code: 8413919520
Length (in): 1.5	Country of Origin: United States

Product Description

Pump Head Repair Kit Compatible with Grainger Part Number 35U539 35U540 35U545 4NA12 4VZG3 4VZG4 Compatible with Manufacturer Model Number 45MFH2A1SUG1 45MJH2A1STAA 45MJH2A3STAA 45MJL2A1STAA 85MFH2A1SUG1 85MJH2A1STG1 Flow Rate (Maximum) 17 gpd Includes Connecting Nuts Latches Ferrules Duckbill Pump Tube Roller Assembly Material Polycarbonate Product Type Pump Head Repair Kit Tubing Connection Size 1/4 in Compatible with Brand Stenner