



STENNER Pump Head Repair Kit 1/4in PC For35U542, 29FJ88

Item **27YBJ1724** Mfr. Model **QP107KG1**

Product Details

Item Reference: 29FJ88	Width (in): 9
Brand: STENNER	Height (in): 8
Weight (lb): 0.59	Harmonization Code: 8413919520
Length (in): 1.5	Country of Origin: United States

Product Description

Pump Head Repair Kit Compatible with Grainger Part Number 35U542 35U543 35U552 4NA13 4VZG5 Compatible with Manufacturer Model Number 45MJH7A1STAA 45MJH7A3STAA 85MFH7A1SUG1 85MJH7A1STG1 85MJH7A3STAA Flow Rate (Maximum) 40 gpd Includes Connecting Nuts Latches Ferrules Duckbill Pump Tube Roller Assembly Material Polycarbonate Product Type Pump Head Repair Kit Tubing Connection Size 1/4 in Compatible with Brand Stenner