



CHAPIN Sprayer Repair Kit, 2ZV95

Item **20ANG4078** Mfr. Model **65378**

Product Details

Item Reference: 2ZV95	Width (in): 10.1
Brand: CHAPIN	Height (in): 2
Weight (lb): 0.76	Harmonization Code: 4009420050
Length (in): 11.1	Country of Origin: United States

Product Description

Sprayer Repair Kit Material Viton For Use With 1949 Includes Seals and Gaskets