



SANI-LAV Hot Faucet Valve Repair Kit, 40D757

Item **22NRP4296** Mfr. Model **1062HL**

Product Details

Item Reference: 40D757	Width (in): 1.2
Brand: SANI-LAV	Height (in): 1.2
Weight (lb): 0.11	Harmonization Code: 8481809015
Length (in): 2	Country of Origin: Taiwan

Product Description

Hot Faucet Valve Repair Kit Finish Chrome plated For Use With Mfr Model Number 2005 2007 Mfr No 2004