



ASC0 Valve Rebuild Kit For 3UL87 3UL88, 2HTW4

Item **22ESA49949** Mfr. Model **302120**

Product Details

Item Reference: 2HTW4	Width (in): 3.7
Brand: ASC0	Height (in): 2.2
Weight (lb): 0.2	Harmonization Code: 8481909085
Length (in): 5.3	Country of Origin: United States

Product Description

Valve Rebuild Kit For Use With Grainger Item Number 3UL87 3UL88 Includes Bonnet Cap Retaining Clip Retaining Core Assembly Holder Assembly I And M Instructions O-Rings Plugnut/Core Tube Assembly Spring Compression Wrench -