



## ASC Valve Rebuild Kit, 4ELW2

Item **22ESA50061** Mfr. Model **302143**

### Product Details

|                              |                                         |
|------------------------------|-----------------------------------------|
| Item Reference: <b>4ELW2</b> | Width (in): <b>2.9</b>                  |
| Brand: <b>ASCO</b>           | Height (in): <b>5.9</b>                 |
| Weight (lb): <b>0.3</b>      | Harmonization Code: <b>8481909085</b>   |
| Length (in): <b>4.1</b>      | Country of Origin: <b>United States</b> |

### Product Description

Valve Rebuild Kit For Use With Grainger Item Number 3UL97 3UL98 For Use With Mfr Model Number 8320G186 120/60 110/50 EF 8320G186 120/60 110/50 Includes Body Gasket Bonnet Gasket Core Assembly Core Spring Disc Disc Holder And Spring Plug nut Core Tube Sub-Assembly Valve Bonnet -