sales@murada.co.id
www.murada.co.id



ASCO Valve Rebuild Kit For 3UL49, 2HTX1

Item **22ESA49954** Mfr. Model **302020**

Product Details

Item Reference: **2HTX1**	Width (in): **3.8**
Brand: **ASCO**	Height (in): **2.4**
Weight (lb): **0.25**	Harmonization Code: **8481909085**
Length (in): **5.3**	

Product Description

Valve Rebuild Kit For Use With Mfr Model Number 8262G007 Includes Cap Retaining Clip Retaining Core Assembly I And M Instructions Lubricant O-Rings Solenoid Base Sub Assembly Spring Compression -