sales@murada.co.id
www.murada.co.id



ZURN WILKINS RP Repair Kit, 41TL60

Item **22IVM50405** Mfr. Model **RK34375**

Product Details

Item Reference: **41TL60**	Width (in): **5**
Brand: **ZURN WILKINS**	Height (in): **2**
Weight (lb): **0.31**	Harmonization Code: **8481909085**
Length (in): **7**	

Product Description

RP Repair Kit Fits Brand Zurn For Use With Grainger Item Number 45K857 45K858 For Use With Mfr Model Number 12-375XL 34-375XL Includes Check assembly #1 and #2 O-Ring Cover O-Ring Housing Inlet O-Ring Housing Outlet O-Ring Seat O-Ring Sleeve Relief Valve Seat Relief Valve Spring Relief Valve Stem Assembly