sales@murada.co.id
www.murada.co.id



ZURN WILKINS RP Repair Kit, 41TL61

Item **22IVM50406** Mfr. Model **RK1375**

Product Details

Item Reference: **41TL61**	Width (in): **5**
Brand: **ZURN WILKINS**	Height (in): **2.1**
Weight (lb): **0.48**	Harmonization Code: **8481909085**
Length (in): **7.1**	

Product Description

RP Repair Kit Fits Brand Zurn For Use With Grainger Item Number 45K859 For Use With Mfr Model Number 1-375XL Includes Check Assembly Check Assembly #1 and #2 O-Ring Cover O-Ring Housing Inlet O-Ring Housing Outlet O-Ring Seat O-Ring Sleeve Relief Valve Seat Relief Valve Spring Relief Valve Stem Assembly